

## HI-GLOSS ALUMINUM PAINT

AMF - S008

Page 1 of 1

DESCRIPTION e pack, high gloss alkyd aluminum prior/exterior use in mild industrial vater and heat resistance (up to 200 n. MMENDED USES strate such as steel, aluminum, and sed for storage tanks, refineries, , and ducts.	SYSTEM RECOMMENDATION   Iron, Steel, Aluminum, Galvanized Steel:   Zinc Chromate Primer 1 Coat 50 Microns DFT   Hi-Gloss Aluminum Paint 2 Coats 25 Microns DFT   Iron and Steel (Self Prime): Iron so Steel (Self Prime):   Hi-Gloss Aluminum Paint 2 Coats 25 Microns DFT   Previously Painted Surfaces: Surfaces should be free from all
erior/exterior use in mild industrial vater and heat resistance (up to 200 n. <b>MMENDED USES</b> strate such as steel, aluminum, and sed for storage tanks, refineries, , and ducts.	Zinc Chromate Primer Hi-Gloss Aluminum Paint1 Coat 2 Coats50 Microns DFT 25 Microns DFT per coatIron and Steel (Self Prime):Hi-Gloss Aluminum Paint2 Coats25 Microns DFT per coat
strate such as steel, aluminum, and sed for storage tanks, refineries, , and ducts.	Hi-Gloss Aluminum Paint 2 Coats 25 Microns DFT per coat
sed for storage tanks, refineries, , and ducts.	per coat
ARACTERISTICS	Previously Painted Surfaces: Surfaces should be free from all
Silver Bright Aluminum $41\% \pm 1\%$ $0.94$ KGs / Itr $\pm 2\%$ 25 Microns $16.4 \text{ m}^2$ / Itr or $62.20 \text{ m}^2$ / US gallon $30 \degree \text{C}$ <b>Dry to Touch:</b> 2 Hours <b>To Handle:</b> 6 Hours <b>To Recoat:</b> 12 Hours 18 months, unopened at 25 $\degree \text{C}$ Thinner YTF – K099	foreign material. Old paint films must be brush blasted or scuff sanded prior to coating. Unknown old paint surface should be tested for lifting or peeling. If it does, clean to sound substrate and treat as new surface. *For further information on recommended products please refer to Sherwin Williams Saudi Arabia Painting & Coatings System Guide. **For further information on surface preparation methods and application procedures please refer to Sherwin Williams Saudi Arabia Surface Preparation bulletin.
TION PROCEDURES	SPECIAL TIPS
<u>Surface Preparation:</u> Surface must be dry, clean and in sound condition. Remove oil, dust, dirt, millscale or other foreign substance to ensure good adhesion. Minimum surface preparation methods to be followed for (1) Iron and Steel – SSPC-SP2 or SP3 (2) Aluminum and Galvanizing – SSPC-SP1 (3) Concrete should be cured, dry and clean. Allow weathering	Excessive reduction of material can affect the film build, appearance, and adhesion. Any further specific technical information can be obtained from SWSA if you email ask@sherwinwilliams.ae
	SAFETY PRECAUTIONS
Reduce 5% with paint thinner Reduce as required for suitable spray Reduction not recommended	Spray under well-ventilated conditions. Do not breathe or inhale mist. When spraying, wear air mask. Avoid skin contact. Spillage on skin should immediately be removed with suitable cleanser, soap and water. Eyes should be flushed with water and medical attention sought immediately.
fuce	0.94 KGs / Itr <u>+</u> 2% 25 Microns 16.4 m <sup>2</sup> / Itr or 62.20 m <sup>2</sup> / US gallon 30 °C Dry to Touch: 2 Hours To Handle: 6 Hours To Recoat: 12 Hours 18 months, unopened at 25 °C Thinner YTF – K099 TION PROCEDURES face must be dry, clean and in sound ust, dirt, millscale or other foreign od adhesion. Minimum surface a followed for (1) Iron and Steel – ninum and Galvanizing – SSPC-SP1 ed, dry and clean. Allow weathering six months prior to coating. Reduce 5% with paint thinner Reduce as required for suitable spray